



## **PRODUCT INFO**

**Flanged clamps FSZ** of die-cast aluminum have a slitted clamping point machined with cutting methods.

The flange with two bores serves as an interface or for fastening the clamp to the place of use.

The bore at the clamping point is arranged in the plane parallel to the face of the flange. It receives typically available construction tubes with full surface contact over the entire cross-section of the bore.

At the screw point, a hex socket cap screw or an adjustable hand lever reduces the bore cross-section for clamping.

Adjustable hand levers are intended for repeated, tool-free clamping. Under the designation HSK, these are available separately for individual use and in other designs. Compared with the tooloperated hex socket cap screw, the clamping force achievable with an adjustable hand lever is lower due to the shorter lever length.

**RoHS-compliant product** 





Clamping point	Clamaina	d₂	I,	I <sub>2</sub>	m	t	X <sub>1</sub>	У1	<b>y</b> 2	Hex socket cap screw	Accessories recom. hand lever	
Bore d <sub>1</sub>	Clamping length <b>k</b>										HSK for z lever length <b>l<sub>3</sub></b>	
B 20	40	6,5	62	40	30	7	52	70	53	M 8-25	-	
B 25	40	6,5	62	40	30	7	52	70	53	M 8-25	78	
B 30	40	6,5	62	40	30	7	52	70	53	M 8-25	78	
B 30	56	8,5	83	56	42	10	78	108	82	M 10-35	-	
B 32	56	8,5	83	56	42	10	78	108	82	M 10-35	-	
B 35	56	8,5	83	56	42	10	78	108	82	M 10-35	92	
B 40	56	8,5	83	56	42	10	78	108	82	M 10-35	92	

## Screw point

Z	
1	Hex socket cap screw steel, zinc-plated DIN 912-8.8 and lock nut steel DIN 985-8, zinc-plated
2	Hex socket cap screw stainless steel DIN 912-A2-70 and lock nut stainless steel DIN 985-A2, glide coating

Surl	ace
2	textured powder-coated, Black RAL 9005
8	blasted, matt

	FSZ	- d <sub>1</sub> ·	- k -	<b>z</b> -	0

## ACCESSORIES

- Adjustable hand levers HSK see page 168

## **ON REQUEST**

- Clamping point with special diameter
- Screw point with hex head screw

 Surface ball-burnished, anodized or powder-coated in other RAL colors 50

20

**B** 

Z

9

Ē



Clamping point Clamping length

Screw point

Surface